

# CRS PATCH 10.0.1

CRS Software Note 9 contains the instructions for loading and installing CRS Patch 10.0.1, which includes an AWIPS authorization file that stores the valid processors to use for AWIPS connectivity tests. If for any reason sites need to re-install the CRS application (installing a new MP or FEP hard drive, old software is corrupted, etc.), they must re-load the 10.0.1 patch following the installation of CRS Build 10.0.

Sites should plan on completing the patch installation by October 24.

Oracle Workflow Notification (FYI)

---

—

Date: 26-AUG-05

CRS Software Note 9 - CRS Build 10.0.1 Software Installation Procedures

CRS Software Note 9, CRS Build 10.0.1 Software Installation Procedures, has been released. This document contains the procedures for installing the Console Replacement System (CRS) Build 10.0.1 software. The tasks necessary for installing the software are included in Attachment A. Click the link below to download/print the document.

[https://www.ops1.nws.noaa.gov/Secure/CRS/crs\\_software\\_notes/CRSswNote9build10-0-1\\_S.pdf](https://www.ops1.nws.noaa.gov/Secure/CRS/crs_software_notes/CRSswNote9build10-0-1_S.pdf)

## **Please note there are two errors in the note:**

1. Page 1 states that there is a CRS Build 10.0.1 installation application CD that is being issued by W/OPS12. This is incorrect - there is no CD - the patch is downloaded from the NOAA1 server.
2. The sample EMRS report on page B-1 is incorrect. The modification number in block 17a must be "S9". Also, the Maintenance Comments in block 15 also should reflect Software Note 9.